

**BROKEN TAP REMOVER** 

# QUICK SOLUTION TO BROKEN TAP,

# NO MORE HEADACHE!

Fast, low cost, high performance, JOEMARS TR100 BROKEN TAP REMOVER, your most reliable partner!



#### **FEATURES:**

- · Light, small, portable, compact design.
- High speed & high efficiency and low cost.
- Simple operation, easily remove broken tap.
- Full power source choices: 100V/110V/120V/200V/220V/230V/240V,
- 1 PHASE, 50HZ/60HZ,
- Dielectric:

Using ordinary tap water as machining dieletric liquid.

• Electrode:

Using any brass bar as electrode.

• Flexibility:

Machining easily even on a large workpiece.

• No damage:

Remove taps easily without damage the threads.


Complete functions:

Auto feed, depth setting (stop at a specific depth), selectable arcing timer, auto retract, workhead swivel alarm messages: depth arrival, arcing, over-temp.


More applications:

Starting holes for Wire Cut EDM. Cutting Tungsten Carbide or any harden steel.


### ■ MACHINING APPLICATIONS:



# Build a pool on the workpiece surface by using putty. PUTTY. WORKPIECE



## ■ HOW TO REMOVE BROKEN TAP:



# ■ SPECIFICATIONS:




# ■ STANDARD ACCESSORIES:


1.Generator
2.Machine unit
3.Chemical clay
4.Chuck handle
5.Brass electrode bar
Ø1.5mm x4PCS
Ø2.0mm x2PCS
Ø2.5mm x2PCS
Ø3.0mm x2PCS
Ø4.0mm x1PC
Ø5.0mm x1PC

**OJOEMARS** 

# **■WORKHEAD SWIVEL:**



### **■ DIMENSIONS:**



## JOEMARS MACHINERY & ELECTRIC INDUSTRIAL CO., LTD.

No. 66, Lane124,Sec.1,Youyuan Road,Tatu District, Taichung , Taiwan 432

Ø6.0mm x1PC

Tel: 886-4-2691-7566 Fax: 886-4-2691-7555